

March 1st, 2010

NOTICE / ELECTRIC CONTROL BOXES

Snowblowers:

	<i>Versatile 48'' Model 700480-2</i>
	<i>Versatile 54'' Model 700460-3</i>
	<i>Vantage 66'' Model 700512</i>
	<i>Vantage 72'' Model 700513</i>

For the products mentioned above, we have experienced some problems with the electric control boxes. If you have purchased one of these models of snowblowers (product bought since the summer of 2009, which have a serial number starting with 9xxxxx), you will automatically receive a new control box from your dealer. Delivery is scheduled for some time in June 2010.

In the mean time, if your snowblower becomes unusable because of this problem, we invite you to contact your dealer to obtain a temporary alternative until the new control box arrives.

Rest assured that we care about your satisfaction and it is of the up most importance to us. Whether you have experienced problems or not with the control box, it may wear out pre-maturely. Therefore, since this component does not meet our quality standards or our durability standards, we prefer replacing it, since our main goal is to offer high performance, long lasting equipment that gives you many years of pleasure.